



TECHNICAL NOTICE

September 19, 2011

USE OF RADIANT BARRIERS WITH METALWORKS® STEEL SHINGLES*

Use of radiant barriers in conjunction with TAMKO MetalWorks Shingles is acceptable, provided all requirements of the MetalWorks Steel Shingle Installation Guide are followed. Be advised that radiant barriers may create inadequate ventilation or form a vapor barrier in certain installations, which may lead to vapor condensation and moisture accumulation in the attic space, deterioration of insulation, wood and other construction materials, development of mold and mildew, and ice damming on the roof. Ensuring proper installation of the radiant barrier, incorporation of adequate ventilation, and appropriate management of moisture are the responsibility of the building owner, design professional, and contractor.

This document is not intended nor should it be construed to modify or alter the terms of TAMKO's MetalWorks Steel Shingles 50-Year Limited Warranty.

Additional information about TAMKO products is available at tamko.com.

* To obtain the current version of this Technical Notice, visit TAMKO's website at tamko.com.