



TECHNICAL NOTICE

August 28, 2019

USE OF RADIANT BARRIERS WITH METALWORKS® STEEL SHINGLES*

Use of radiant barriers in conjunction with TAMKO® MetalWorks® Steel Shingles is acceptable, provided all requirements of the *MetalWorks Steel Shingle Installation Guide* are followed. Be advised that radiant barriers may create inadequate ventilation or form a vapor barrier in certain installations, which may lead to vapor condensation and moisture accumulation in the attic space, deterioration of insulation, wood and other construction materials, development of mold and mildew, and ice damming on the roof. Ensuring proper installation of the radiant barrier, incorporation of adequate ventilation, and appropriate management of moisture are the responsibility of the building owner, design professional, and contractor.

This document is not intended nor should it be construed to modify or alter the terms of TAMKO's *MetalWorks Steel Shingles 50-Year Limited Warranty and Arbitration Agreement*.

Additional information about TAMKO products is available at tamko.com.

* To obtain the current version of this Technical Notice and the most recent limited warranty, visit TAMKO's website at tamko.com. TAMKO reserves the right to update, remove, or otherwise modify any Technical Notice. If a previous Technical Notice currently is not listed at tamko.com then it is no longer valid and should not be referenced or relied upon for any reason.

©2019 TAMKO Building Products LLC. TAMKO, TAMKO logo, and MetalWorks are registered trademarks of TAMKO Building Products LLC.